



KITPLANES FOR AFRICA

www.saplanes.co.za

P.O.Box 326

KOMATIPOORT

1340

South Africa

Rick Burrough 082 410032

Stefan Coetzee 082 6018970

info@saplanes.co.za

SERVICE LETTER

AIRCRAFT EFFECTED: All models

BULLETIN NUMBER: SB012

ORIGINAL ISSUE DATE: 29-05-00

REVISION DATE: 17-11-08

SUBJECT: Tyre inflation

APPLICABILITY: All

COMPLIANCE: Advisory

Problem: Over inflated tyres can cause axles to shear.
The tyres form an important part of the suspension system.
Under inflated tyres can cause tyre creep and shearing off of inflation valves.

Solution: Correct tyre inflation is 0.75 bar to 1.0 bar.