



KITPLANES FOR AFRICA

www.saplanes.co.za

P.O.Box 326

KOMATIPOORT

1340

South Africa

Rick Burrough 082 4100032

Stefan Coetzee 082 6018970

info@saplanes.co.za

SB #	Subject	1st Issue	Revised	Affected	Compliance
SB001	Tail-post insert	01-07-95	14-11-08	BB 001-015	Mandatory
SB002	Short axle-tube	01-07-95	14-11-08	BB 001-015	Mandatory
SB003	Wrong aileron mixer	01-07-95	14-11-08	BB 001-015	Mandatory
SB004	Wrong jury struts	01-07-95	14-11-08	BB 001-015	Mandatory
SB005	Lift-Strut bolt length	01-07-95	14-11-08	All	Mandatory
SB006	Old flaperon chord length	01-07-95	14-11-08	BB 001-019	Mandatory
SB007	Correct bungee tension	01-07-95	16-11-08	All fitted	Mandatory
SB008	Fuel-Cap Vent	10-12-95	16-11-08	All	Mandatory
SB009	Carb overflow pipe	10-12-95	16-11-08	All fitted	Mandatory
SB010	Nose landing gear	10-12-95	17-11-08	BB,EXP all fitted	Mandatory
SB011	Control torque tube crack	01-12-00	17-11-08	All	Mandatory
SB012	Axle shear	01-12-00	17-11-08	All	Mandatory
SB013	Nose gear V brace	04-04-02	17-11-08	BB all fitted	Mandatory
SB014	Axle bolt length	01-09-02	18-11-08	All	Mandatory
SB015	Stabilizer tabs broken	01-09-02	18-11-08	All	Mandatory
SB016	582 engine mount isolator rubbers	01-10-03	18-11-08	BB, EXP fitted	Mandatory
SB017	Rudder cable ferrule crimp	30-10-03	18-11-08	All	Mandatory
SB018	Tail wheel block lube	01-03-05	18-11-08	All fitted	Mandatory
SB019	Control rod-end failure	23-11-05	18-11-05	All	Mandatory
SB020	Fiberglass seat support	23-12-06	19-11-08	All	Mandatory
SB021	Welded axle backing plate	23-12-06	19-11-08	All fitted	Mandatory
SB022	Throttle control bellcrank	30-12-06	19-11-06	All fitted	Mandatory
SB023	Nose-wheel axle bolts	13-11-07	19-11-08	All fitted	Mandatory
SB024					
SB025					
SB026					
SB027					
SB028					
SB029					
SB030					
SB031					
SB032					
SB033					
SB034					
SB035					
SB036					
SB037	Last MJ sb reviewed SB028				