



KITPLANES FOR AFRICA

www.saplanes.co.za

P.O.Box 326

KOMATIPOORT

1340

South Africa

Rick Burrough 082 4100032

Stefan Coetzee 082 6018970

info@saplanes.co.za

SERVICE BULLETIN

AIRCRAFT EFFECTED: Bushbaby

BULLETIN NUMBER: SB002

ORIGINAL ISSUE DATE: 04-04-02

REVISION DATE: 14-11-08

SUBJECT: Axle tube too short.

APPLICABILITY: SN001 - SN015

COMPLIANCE: Mandatory.

PROBLEM: Some of the early Bushbaby landing gear legs were made with the Ø16mm ID axle tubes too short which will not allow proper installation of the wheel and brake in accordance with the build manual.

The correct length for the axle tube is 125mm.

SOLUTION: Contact the factory or turn a bush out of mild steel to make up the correct axle tube length.